

Oxpho-Blue is an easily applied, highly rust resistant, bright phosphatizing chemical for touching-up or bluing guns, tools and instruments. Leaves no after-rust. Finish gives maximum durability against corrosion, abrasion, handling.



WARNING



WARNING: MAY BE FATAL IF SWALLOWED - CORROSIVE - Contains Phosphoric Acid, Cupric Sulfate and Selenious Acid. Do not take internally. If swallowed: Induce vomiting if victim is conscious and not vomiting. A diuretic will speed elimination of selenium. Vitamin B Complex, Vitamin C and Methionine supplements are recommended. Consult physician immediately. Read carefully other cautions on side panel.

KEEP OUT OF REACH OF CHILDREN

WARNING: IRRITANT - Avoid contact with eyes and skin. For eyes: Flush thoroughly with water for at least 15 minutes. Instillation of aqueous 10% sodium thiosulfate solution is also recommended. Consult physician immediately. For skin: Remove contaminated clothing. Wash thoroughly with soap and water. Application of a 10% sodium thiosulfate cream is also recommended. Avoid vapors: Use with adequate ventilation. If inhaled: Move to fresh air. If misting is likely - use self contained breathing apparatus. Diuretics speed elimination of selenium. Vitamin B Complex, Vitamin C and Methionine supplements are recommended. Consult physician immediately. Wear rubber gloves, apron and goggles. Store in acid resistant container. Do not store in open or unlabeled containers. Wash before smoking or eating.

DIRECTIONS FOR USE

To Re-Touch Old Blue:

1. Remove excessive rust with fine abrasive cloth. Thin oil and thin rust need not be removed.
2. Dampen small cotton pad with Oxpho Blue and rub area to be re-touched until colored.
3. Wipe dry with clean cloth and burnish bright with #0 steel wool or finer.
4. If deeper color is desired, repeat Steps 2 and 3.

To Re-Blue Entire Gun:

1. Brighten gun with abrasive and clean with alcohol.
2. Saturate thumb-sized cotton swab with solution and cover entire gun, dipping in solution with each pass. Areas not darkening should be #0 steel-wooled and solution re-applied.
3. Allow to work without drying 60 seconds and wipe nearly dry in one pass with a clean cloth.
4. When completely dry, burnish with #0 steel wool, or finer.
5. Apply thin darkening coat with small, dampened cotton pad.
6. Wipe dry and burnish with #0 steel wool.
7. For darker color repeat Steps 5 and 6.

BROWNELLS[®] OXPHO-BLUE[™] LIQUID GUN BLUE

1 Pint/16 FL. OZ./473ml #082-024-016



READ & FOLLOW THESE
INSTRUCTIONS

BROWNELLS[®]

SELECTION. SERVICE. SATISFACTION.[™]

200 S. Front St. Montezuma, IA 50171
800-741-0015 or 641-623-4000 • www.brownells.com